



Oil Companies International Marine Forum

Offshore Vessels Inspection Database (OVID)




OVIQ

Report Number	XNLR-4597-8496-4419
Report Template	OVIQ2 (7105)
Vessel Name	SMS Valiant
IMO Number	9581394
Date of Inspection	16 Sep 2015
Port of Inspection	Kali Baru Jetty Marunda, Jakarta
Inspecting Company	Chevron Shipping Co. LLC

TURNING CIRCLES AT MAX. RUDDER ANGLE


LOADED Water depth/draught ratio = 1.2

BALLAST



1 cable =
0.1 nautical mile

EMERGENCY MANOEUVRES




FULL SEA AHEAD


Comparison of turning (max. rudder) and full astern stopping ability (rudder amidships)

LOADED

BALLAST



EMERGENCY MANOEUVRES



FULL SEA AHEAD

Comparison of turning (max. rudder) and full astern stopping ability (rudder amidship)